

Benteler de México S.A. de C.V. - Stamping plant

Contracting Entity: Calle Acacias Nave 10, Parque Industrial Finsa, C.P. 72710, Cuautlancingo, Puebla, México

Bureau Veritas Certification Holding SAS – UK Branch certifies that the Management System of the above organisation has been audited and found to be in accordance with the requirements of the management system standards detailed below

Standard

ISO 14001:2015

Scope of Certification

Manufacture of Stamping and Assembly of metal parts for the Automotive Industry.

Original cycle start date:
Expiry date of previous cycle:
Certification/ Recertification Audit date:
Certification/ Recertification cycle start date:

30-June-2004 08-June-2022 03-March-2022 29-July-2022

Subject to the continued satisfactory operation of the organization's Management System, this certificate expires on: **08-June-2025**

Certificate No.: CO22.00331/U Version: 1 Previous Certificate No.:CO19.00158/U Revision date: 29-July-2022



Certification Body Address: 5th Floor, 66 Prescot Street, London E1 8HG, United Kingdom.

Local Office:

BVQI Mexicana, S.A. de C.V. - Blvd. Manuel Ávila Camacho No. 36, Piso 11 Col. Lomas de Chapultepec III Sección, Miguel Hidalgo, C.P. 11000 Ciudad de México

Further clarifications regarding the scope and validity of this certificate, and the applicability of the management system requirements, please call: +52 55 5351 8000/ 9000.



Rev. 3.10